## 16-176-18

## Post Emergency Report

SCA Chemical Services
11700 S. Stony Island Avenue
Chicago, Illinois 60617



Owner/Operator	Banks Clark, Facilit	y Manage <b>r</b>	
Facility Name	SCA Chemical Services	s, Inc.	·
Address	11700 S. Stony Island	I Avenue	· .
	Chicago, Illinois 60	0617	
Telephone	(312) 646-5700		
· · ·			
Date of Incident	t <u>August 8, 1983</u>	. Time 11:30	AM
Type of Incident	fire in rotary kiln	feed hopper	
2-16 gallon plas	stic drums) of waste p	aint and solvents (com	allons (contained in posed of methyl alcohol  15%, xylene at approx-
			llon fiber drums containing
	•		
	solvent clean-up mate	•	
*	es <u>no injuries have o</u> c	ccurred or were allege	d as a result of this
incident.	···		
Assessment of act	tual or potential haza	ards to human health o	or the environment
The fire and exti	inguishing materials w	ere contained and rest	ricted to a diked
area around the r	rotary kiln on SCA pro	perty. Water and other	er_extinguishing
materials were re	ecovered and transferr	ed to a waste storage	tank on SCA property.
No waste or waste	material went to the	sewers or the Sanitar	y District. Smoke
emission from the	fire and steam and m	ists generated by ext	inguishment were
minimal, lasting	for approximately 3-1	5 minutes, All SCA pe	rsonnel were evacuated
from the facility	as a safety measure e	except for SCA personn	el experienced in
	o were equipped with a	respiratory protection	

Contingency Plan functioned properly.

Estimated quantity and disposition of recovered materials Approximately							
6,000 gallons of water was rec	overed from extinguishment of the fire. This						
water was transferred to a was	te storage tank for incineration in the SCA						
incinerator.							
	,						

RO5-8303-018 H-176-18

## Post Emergency Report

SCA Chemical Services
11700 S. Stony Island Avenue
Chicago, Illinois 60617

	Banks Clark, Facility Manager	
Facility Name	SCA Chemical Services, Inc.	
Addres <b>s</b>	11700 S. Stony Island Avenue	
	Chicago, Illinois 60617	
Telephone	(312) 646-5700	
	t December 8, 1983 Time 4:20 PM Unplanned environmental release (emissions) from incinerator emergen t stack. This incident was caused by emergency shutdown resulting fro	
Name and quanti	loss of instrument air due to freezing of lines. ty of materials involved	
<del>-</del>	ck opened; emissions not scrubbed by acid removal and particulate	
removal system	ns. Particulates and acidic combustion gases.	
· .		
Extent of injuri	ies None known or alleged.	
Assessment of ac	tual or potential hazards to human health or the environment	•
Short term par	ticulate and acidic gas release should have minor effects	
due to wind di	spersion.	
	<i>r</i>	

Estimate	d quantity	and dispos	ition of	recovere	d materials	No emissio	ns
were re	ecovered.	• •	•	· · · · · · · · · · · · · · · · · · ·	,		
,1		• .					
							,

<sup>\*</sup> Contacted Jim Kelly, Supervisor Emergency Response Unit and Geoffrey Langley of ESDA at time of release.